

MHD Contractor Performance: January - March 2015						
CONTRACTOR	UNITS COMPLETED	* % OF RE-WIPES TAKEN	LEAD SAFETY VIOLATIONS ISSUED	* PERMIT EXTENSIONS	OPEN COMPLAINTS	
FAQ	7	9.1%	0	1	NO	
C & E	2	9.1%	0	0	NO	
MEDINA	1	0.0%	0	0	NO	
ARL	0	0.0%	0	1	NO	
GET	0	0.0%	0	1	NO	
NO ACTIVITY DURING THE QTR						
EPM						
POWER						
RIGHT PRICE						
<p><b>* % OF REWIPES TAKEN</b> - At the end of the project a dust test is done for occupant safety. When a contractor leaves too much lead dust behind, (measured by lab analysis) he must return to the property for a second cleaning on surfaces where he failed the dust test. The inspector also returns to the site to take more samples to confirm safety.</p> <p><b>*PERMIT EXTENSIONS</b> - Extra time given to contractor to complete the project (ORIGINAL ALOTTED TIME is 2 WEEKS).</p>						